



PCN Tracking Number: PCN\_FT\_024

Issue Date: 2016-10-05

## Product Change Notification

<b>Product Part Number</b>	<b>FT4222HQ Hi-Speed Quad SPI/I2C device</b>	<b>Estimated implementation date</b>
<b>Description of Change</b>	<b>Update from Rev B to Rev C to fix some issues</b>	<b>Oct 2016</b>
<b>Reason for Change</b>	<b>Fix existing issues and improve SPI/QSPI performance.</b>	
<b>Detailed Description</b>	<b>All issues listed below have been fixed:</b> <b>Issue A : Custom PID could not be changed</b> <b>Issue B : Abnormal response after host restart</b> <b>Issue C : Single mode SPI master data lost and no response issues</b> <b>Issue D : SPI/QSPI Performance improvement</b>	
<b>Impact to Data sheet</b>	<b>Function no change</b>	
<b>Benefit of Change</b>	<b>Issues fixed and performance improvement</b>	
<b>Markings to distinguish revised from:</b>	<b>Device date code will be changed to a "C" to indicate revision C</b>	
<b>Sample Availability</b>	<b>Oct 2016</b>	
<b>Risk Assessment, Fit Form and Function &amp; reliability</b>	<b>Fit: Dimension have not changed.</b> <b>Form : Visual appearance is unchanged except for markings for rev C</b> <b>Function: Fix bugs listed above to improve overall performance</b>	
<b>PDF Download</b>	<a href="http://www.ftdichip.com/Support/Documents/ProductChangeNotifications/PCN_FT_024.pdf">http://www.ftdichip.com/Support/Documents/ProductChangeNotifications/PCN_FT_024.pdf</a>	

**Others:**

For the details, please refer the Technical notes:

[http://www.ftdichip.com/Support/Documents/TechnicalNotes/TN\\_161\\_FT4222H%20Errata%20Technical%20Note.pdf](http://www.ftdichip.com/Support/Documents/TechnicalNotes/TN_161_FT4222H%20Errata%20Technical%20Note.pdf)

and

[http://www.ftdichip.com/Support/Documents/TechnicalNotes/TN\\_170\\_FT4222H%20Rev.C%20Technical%20Note.pdf](http://www.ftdichip.com/Support/Documents/TechnicalNotes/TN_170_FT4222H%20Rev.C%20Technical%20Note.pdf)